Michael O. Leavitt

Governor

# State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING



gh

1594 West North Temple, Suite 1210

PO Box 145801

Salt Lake City, Utah 84114-5801

801-538-5340

Lowell P. Braxton 801-359-3940 (Fax)

Division Director 801-538-7223 (TDD)

Partial: XXX Complete: Exploration:

Inspection Date & Time: <u>2/25/99 / 11:00a.m.-3:00p.m.\*</u>

Date of Last Inspection: <u>1/25/99</u>

Mine Name: <u>Dugout Canyon</u> County: <u>Carbon</u> Permit Number: Action S						
Permittee and/or Operator's Name: Canyon Fuel Company						
Business Address: P.O. Box 1029, Wellington, Utah 84542						
Type of Mining Activity: Underground XXX Surface Prep. Plant Other						
Company Official(s): Ken Payne						
State Officials(s): Steve Demczak Federal Official(s): None						
Weather Conditions: 20's, Clear, 6" Snow						
Existing Acreage: Permitted-4035 Disturbed-20.1 Regraded- Seeded- Bonded-						
Increased/Decreased: Permitted Disturbed Regraded Seeded Bonded						
Status:Exploration/XXX Active/_Inactive/_Temporary Cessation/_Bond Forfeiture						
Reclamation (_Phase I/_Phase II/_Final Bond Release/_LiabilityYear)						

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

#### Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

1. 2.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE SIGNS AND MARKERS	EVALUATED [XX] [XX]	<u>N/A</u> [ ]	COMMENTS [XX] [XX]	NOV/ENF
3.	TOPSOIL		$\Box$		$\Box$
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[XX]	Ц	[XX]	$\Box$
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[XX]	Ц	[XX]	ĻĻ
C.	OTHER SEDIMENT CONTROL MEASURES	ĻĻ	ĻĻ	Ц	ĻĻ
d.	WATER MONITORING	Ļļ	Ц	Ļļ	ĻĻ
e.	EFFLUENT LIMITATIONS	Ļļ	ЦĻ	H	ĻĻ
5.	EXPLOSIVES  DISPOSAL OF EXCESS SPON (FILL SUPENIONES)		Ļ	H	닏
6. 7.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS		ᆛ	[VV]	Į.
8.	NONCOAL WASTE	[ <u>XX]</u> [XX]	Ӊ	[XX] [XX]	Ӊ
9.	PROTECTION OF FISH, WILDLIFE AND		ш	ĪVVĪ	ш
٦.	RELATED ENVIRONMENTAL VALUES	r ı	r ı	r 1	Гì
10.	SLIDES AND OTHER DAMAGE	<u>↓ ↓</u> [ ]	<del>   </del>	<del>     </del>	H
11.	CONTEMPORANEOUS RECLAMATION	<del>     </del>	<del>   </del>	7	+
12.	BACKFILLING AND GRADING	<del>[ ]</del>	<del>   </del>	Ħ	<del>-</del>
13.	REVEGETATION	Ħ	H	Ħ	Ħ
14.	SUBSIDENCE CONTROL	Ħ	7	Ħ	Ħ
15.	CESSATION OF OPERATIONS	11	Ħ	Ħ	Ti .
16.	ROADS:				. —
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[ ]	Ш	$\Box$	- Ц
b.	DRAINAGE CONTROLS	Π		$\Box$	$\Box$
17.	OTHER TRANSPORTATION FACILITIES	īī	$\Box$	$\Box$	$\Box$
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	$\overline{XX}$	$\Box$	$\overline{[XX]}$	
19.	AVS CHECK (4th Quarter-April, May, June)(date)		$\Box$	П	
20.	AIR QUALITY PERMIT		ĹĨ	ΙĪ	ΞĪ
21.	BONDING & INSURANCE	[]	ΓĪ	ĪΪ	ΪÌ

### INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: <u>ACT/007/039</u>

DATE OF INSPECTION: 2/25/99

(Comments are Numbered to Correspond with Topics Listed Above)

#### 1. PERMIT-

The permittee will be submitting an amendment to change the design of transporting water to the sediment pond. It will also include designs for additional riprap of inlets and outlet areas.

#### 2. SIGNS AND MARKERS -

Identification signs meet the requirements of the R645 Coal Rules. The perimeter markers were spot-checked and are located around the perimeter of the disturbed areas.

### **4A.** DIVERSIONS -

The diversions have not been installed yet.

# **4B. SEDIMENT PONDS -**

The sediment pond is completed with the with exception of installing an additional diversion to the pond. A new design will be submitted in the near future. The permittee will also submit additional riprap designs.

# 7. REFUSE -

There was no refuse being stacked or stored at Dugout mine.

# 8. NON-COAL WASTE -

The area was clear of non-coal waste material.

# 18. SUPPORT FACILITIES -

The permittee is in the process of building the new sub-station, reclaim tunnels, and footers for crusher and truck loadout building.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: <u>Chris Hansen (Canyon Fuel)</u> <u>Henry Austin (OSM)</u>
Given to: <u>Joe Helfrich (DOGM)</u> Filed to: <u>Price Field Office</u>

Date: February 26, 1999

Inspector's Signature: Stephen I Demozak

#39